

## **EB039 – USB232 – Driver Installation**

This document explains both how to install the drivers for the USB232 E-Block onto the PC. The instructions are currently for XP Professional only.

### **Requirements**

- PC with the following
  - Matrix COM Port drivers
  - Spare USB port

### **Driver Installation**

1. Plug the EB039 unit into the Multiprogrammer.
2. The “Found new hardware” wizard will appear. Select “Install from a list or specific location (Advanced)” option and click “Next>”.
3. Select “Include this location in the search...” and click the “browse” button. Select the “Matrix COM Port” directory, and click “Next>”.
4. Ignore any messages saying that the software has not passed Windows Logo testing by clicking on the “Continue Anyway” button if such a screen appears.
5. If you are asked to overwrite any existing files, click “No to all”.
6. At the end of this, the wizard will say it has finished. Click “Finish” to continue, but straight away a new instance of the wizard should appear! This will install the COM port driver files.
7. Continue through this wizard in exactly the same way as the previous one.
8. At the end of this wizard, you should see a message saying “Your hardware is now ready to use”.